

# KMP®

know how in modern printing



## ES MUSS NICHT ORIGINAL SEIN.



## THE PERFECT ALTERNATIVE.



Product News  
January-March 2019

ERSETZT/REPLACES	KMP CODE	FARBE/COLOR	SEITEN/PAGES* (CA.)	PASSEND FÜR/SUITABLE FOR	ART.-NR./ART. NO.
------------------	----------	-------------	---------------------	--------------------------	-------------------

INKJET

Brother LC-223BK	B62BX	●	550	Brother DCP-J562DW/DCP-J4120DW,	1529,4001
LC-223C	B62CX	●	550	MFC-J480DW/MFC-J680DW/MFC-J4420DW/	1529,4003
LC-223M	B62MX	●	550	MFC-J880DW/MFC-J4625DW/MFC-J4620DW/	1529,4006
LC223Y	B62YX	●	550	MFC-J5320DW/MFC-J5625DW/MFC-J5620DW/	1529,4009
2x LC-223BK	B62DX	●●	2x 550	MFC-J5720DW	1529,4021
LC-223	B62VX	●●●●	4x 550		1529,4005
Brother LC-225XLC	B63C	●	1.200	Brother DCP-J4120DW/MFC-J4420DW/	1530,4003
LC-225XLM	B63M	●	1.200	MFC-J4620DW/MFC-J4625DW/MFC-J5320DW/	1530,4006
LC-225XLY	B63Y	●	1.200	MFC-J5620DW/MFC-J5625DW/MFC-J5720DW	1530,4009
LC-225XLC/M/Y	B63V	●●●	3x 1.200		1530,4050
Canon PGI-580XXL PGBK	C110	●	600	Canon PIXMA TR7550/TR8550, PIXMA TS6150/	1576,0201
CLI-581XXL BK	C111	●	4.590	TS6151/TS6250/TS6251/TS8150/TS8151/	1577,0201
CLI-581XXL C	C112	●	820	TS8152/TS8250/TS8251/TS8252/TS9150/	1578,0203
CLI-581XXL M	C113	●	760	TS9155/TS9550/TS9551	1578,0206
CLI-581XXL Y	C114	●	824		1578,0209
CLI-581XXL PB	C115	●	9.140		1578,0242
PGI-580XXL PGBK, CLI-581XXL C/M/Y	C110V	●●●●			1576,0205
PGI-580XXL PGBK, CLI-581XXL BK/C/M/Y	C116V	●●●●●			1576,0255
CLI-581XXL BK, CLI-581XXL C/M/Y	C111V	●●●●●			1577,0205
Epson 102 (T03R1)	E182	●	7.500	Epson Ecotank ET-2700/ET-2750/ET-3700/	1642,0001
102 (T03R2)	E183	●	6.000	ET-3750/ET-4750	1642,0003
102 (T03R3)	E184	●	6.000		1642,0006
102 (T03R4)	E185	●	6.000		1642,0009
Epson 104 (T00P1)	E191	●	4.500	Epson EcoTank ET-2710/ET-2711	1648,0001
104 (T00P2)	E192	●	7.500		1648,0003
104 (T00P3)	E193	●	7.500		1648,0006
104 (T00P4)	E194	●	7.500		1648,0009
Epson 105 (T00Q1)	E186	●	8.000	Epson Ecotank ET-7700/ET-7750	1643,0001
106 Photo (T00R1)	E187	●	5.000		1644,0040
106 (T00R2)	E188	●	5.000		1644,0003
106 (T00R3)	E189	●	5.000		1644,0006
106 (T00R4)	E190	●	5.000		1644,0009
Epson 673 (T6731)	E225B	●	2.600	Epson L800/L805/L810/L850/L1800 IST	1639,0001
673 (T6732)	E225C	●	4.700		1639,0003
673 (T6733)	E225M	●	4.700		1639,0006
673 (T6734)	E225Y	●	4.700		1639,0009
673 (T6735)	E225LC	●	4.700		1639,0043
673 (T6736)	E225LM	●	4.700		1639,0046
HP 303XL (T6N04AE)	H178	●	600	HP Envy Photo 6230/7130/7830	1763,4001
HP 303XL (T6N03AE)	H179	●	420		1764,4030
HP 303XL	H178V	●●●●	600, 420		1763,4005
HP 981A (J3M71A)	H169B	●	6.000	HP Pagewide Enterprise Color 556dn/	1754,4801
HP 981A (J3M68A)	H169C	●	6.000	556xh, Pagewide Enterprise Color MFP	1755,4803
HP 981A (J3M69A)	H169M	●	6.000	586dn/586f/586z	1755,4806
HP 981A (J3M70A)	H169Y	●	6.000		1755,4809
HP 981X (L0R12A)	H169BX	●	11.000	HP Pagewide Enterprise Color 556dn/	1754,4001
HP 981X (L0R09A)	H169CX	●	10.000	556xh, Pagewide Enterprise Color MFP	1755,4003
HP 981X (L0R10A)	H169MX	●	10.000	586dn/586f/586z	1755,4006
HP 981X (L0R11A)	H169YX	●	10.000		1755,4009

● black | ● cyan | ● magenta | ● yellow | ● light/photo black | ● light/photo cyan | ● light/photo magenta | ● blue | ● color

ERSETZT/REPLACES	KMP CODE	FARBE/COLOR	SEITEN/PAGES* (CA.)	PASSEND FÜR/SUITABLE FOR	ART.-NR./ART. NO.
------------------	----------	-------------	---------------------	--------------------------	-------------------

TONER, TROMMELEINHEITEN/DRUMS

Canon 040BK (0460C001)	C-T42B	●	6.300	Canon i-Sensys LBP710cx/LBP712cx	3608,0000
040C (0458C001)	C-T42C	●	5.400		3608,0003
040M (0456C001)	C-T42M	●	5.400		3608,0006
040Y (0454C001)	C-T42Y	●	5.400		3608,0009
Canon 040HBK (0461C001)	C-T42BX	●	12.500	Canon i-Sensys LBP710cx/LBP712cx	3608,3000
040HC (0459C001)	C-T42CX	●	10.000		3608,3003
040HM (0457C001)	C-T42MX	●	10.000		3608,3006
040HY (0455C001)	C-T42YX	●	10.000		3608,3009
Canon 041 (0452C002)	C-T44	●	10.000	Canon i-Sensys LBP312x	3610,0000
041H (0453C002)	C-T44X	●	20.000		3610,3000
Canon 052 (2199C002)	C-T43	●	3.100	Canon Canon i-Sensys LBP212dw/LBP214dw/	3609,0000
052H (2200C002)	C-T43X	●	9.200	LBP215x, i-Sensys MF421dw/MF426dw/	3609,3000
				MF428x/MF429x	
Brother TN-421BK	B-T98	●	3.000	Brother DCP-L8410CDW, HL-L8260CDW/	1265,0000
TN-421C	B-T99	●	1.800	HL-L8360CDW, MFC-L8690CDW/	1265,0003
TN-421M	B-T100	●	1.800	MFC-L8900CDW	1265,0006
TN-421Y	B-T101	●	1.800		1265,0009
Brother TN-423BK	B-T98X	●	6.500	Brother DCP-L8410CDW, HL-L8260CDW/	1265,3000
TN-423C	B-T99X	●	4.000	HL-L8360CDW, MFC-L8690CDW/	1265,3003
TN-423M	B-T100X	●	4.000	MFC-L8900CDW	1265,3006
TN-423Y	B-T101X	●	4.000		1265,3009
Brother TN-2410	B-T67	●	1.200	Brother DCP-L2510D/DCP-L2530DW/	1267,0000
TN-2420	B-T68	●	3.000	DCP-L2550DN, HL-L2310D/HL-L2350DW/	1267,3000
				HL-L2370DN/HL-L2375DW, MFC-L2710DN/	
				MFC-L2710DW/MFC-L2730DW/MFC-L2750DW	
Oki 46490404	O-T53	●	1.500	Oki C532dn/C542dn, MC563dn/MC573dn	3361,0000
46490403	O-T54	●	1.500		3361,0003
46490402	O-T55	●	1.500		3361,0006
46490401	O-T56	●	1.500		3361,0009
Oki 46490608	O-T53X	●	7.000	Oki C532dn/C542dn, MC563dn/MC573dn	3361,3000
46490607	O-T54X	●	6.000		3361,3003
46490606	O-T55X	●	6.000		3361,3006
46490605	O-T56X	●	6.000		3361,3009



\*nach/acc to. ISO/IEC 24711, nach/acc to. ISO/IEC 19752, 19798

INKJET

TONER

THERMAL  
TRANSFER

NYLON

FRANKING  
SUPPLIES

OFFICE  
MEDIA

POS

...

ERSETZT/REPLACES	KMP CODE	FARBE/COLOR	PASSEND FÜR/SUITABLE FOR	ART.-NR./ART. NO.	
<b>INKJET</b> Brother LC-3233BK LC-3233C LC-3233M LC-3233Y	B79	●	Brother DCP-J1100DW, MFC-J1300DW	1541,4801	
	B80	●		1542,4803	
	B81	●		1542,4806	
	B82	●		1542,4809	
Brother LC-3235XL-BK LC-3235XL-C LC-3235XL-M LC-3235XL-Y	B83	●	Brother DCP-J1100DW, MFC-J1300DW	1541,4001	
	B84	●		1542,4003	
	B85	●		1542,4006	
	B86	●		1542,4009	
PGI-580 PGBK (2078C001) CLI-581 BK (2106C001) CLI-581 C (2103C001) CLI-581 M (2104C001) CLI-581 Y (2105C001) CLI-581 PB (2107C001)	C118	●	PIXMA TR7550/TR8550, PIXMA TS6150/TS6151/TS6250/TS6251/ TS8150/TS8151/TS8152/TS8250/TS8251/TS8252/TS9150/TS9155/ TS9550/TS9551C	1576,0801	
	C119	●		1577,0801	
	C120	●		1578,0803	
	C120	●		1578,0806	
	C121	●		1578,0809	
	C122	●		1578,0842	
PGI-580XL PGBK (2024C001) CLI-581XL BK (2052C001) CLI-581XL C (2049C001) CLI-581XL M (2050C001) CLI-581XL Y (2051C001) CLI-581XL PB (2053C001)	C124	●	PIXMA TR7550/TR8550, PIXMA TS6150/TS6151/TS6250/TS6251/ TS8150/TS8151/TS8152/TS8250/TS8251/TS8252/TS9150/TS9155/ TS9550/TS9551C	1576,0001	
	C125	●		1577,0001	
	C126	●		1578,0003	
	C127	●		1578,0006	
	C128	●		1578,0009	
	C129	●		1578,0042	
Epson 34XL (T3471) 34XL (T3472) 34XL (T3473) 34XL (T3477)	E222X	●	Epson Workforce Pro WF-3720DWF/WF-3725DWF	1637,4001	
	E223X	●		1637,4003	
	E224X	●		1637,4006	
	E225X	●		1637,4009	
Epson 35XL (T3591) 35XL (T3592) 35XL (T3593) 35XL (T3594)	E226X	●	Epson Workforce Pro WF-4720DWF&/WF-4725DWF/ WF-4730DTWF/WF-4740DTWF	1638,4001	
	E227X	●		1638,4003	
	E228X	●		1638,4006	
	E229X	●		1638,4009	
HP 903XL (T6M15AE) HP 903XL (T6M03AE) HP 903XL (T6M07AE) HP 903XL (T6M11AE)	H177BX	●	HP Officejet 6950 All-in-One, Officejet Pro 6970 All-in-One	1756,4001	
	H177CX	●		1757,4003	
	H177MX	●		1757,4006	
	H177YX	●		1757,4009	
HP 981Y (L0R16A) HP 981Y (L0R13A) HP 981Y (L0R14A) HP 981Y (L0R15A)	H169BXX	●	HP Pagewide Enterprise Color 556dn/556xh, Pagewide Enterprise Color MFP 586dn/586f/586z	1754,4201	
	H169CXX	●		1755,4203	
	H169MXX	●		1755,4206	
	H169YXX	●		1755,4209	
<b>DRUMS</b> Brother DR-3400 Brother DR-1050 Brother DR-2400	B-DR28		Brother DCP-L5500DN/DCP-L6600DW, HL-L5000D etc.	1263,7000	
	B-DR29			Brother HL-1110/HL-1112/HL-1210W/HL-1212W etc.	1260,7000
	B-DR30			Brother DCP-L2510D/DCP-L2530DW/DCP-L2550DN etc.	1267,7000
HP 37A (CF237A)	H-T248	●	HP Laserjet Enterprise Flow MFP M631h/M632z etc.	2544,0000	
<b>TONER</b> HP 87A (CF287A) HP 87X (CF287X)	H-T243A	●	HP LaserJet Pro M501n/M501dn, Enterprise M506dn/M506x etc.	2540,0000	
	H-T238X	●		2540,3000	
TN-243BK TN-243C TN-243M TN-243Y TN-247BK TN-247C TN-247M TN-247Y	B-T109	●	Brother DCP-L3510CDW/DCP-L3550CDW, HL-L3210CW/ HL-L3230CDW/HL-L3270CDW, MFC-L3710CW/MFC-L3730CDN/ MFC-L3750CDW/MFC-L3770CDW	1268,0000	
	B-T110	●		1268,0003	
	B-T111	●		1268,0006	
	B-T112	●		1268,0009	
	B-T109X	●		1268,3000	
	B-T110X	●		1268,3003	
	B-T111X	●		1268,3006	
	B-T112X	●		1268,3009	
Oki 46508716 46508715 46508714 46508713 46508712 46508711 46508710 46508709	O-T51	●	C332dn/C332dnw, MC363dn/MC363dnw	3360,0000	
	O-T57	●		3360,0003	
	O-T58	●		3360,0006	
	O-T59	●		3360,0009	
	O-T51X	●		3360,3000	
	O-T57X	●		3360,3003	
	O-T58X	●		3360,3006	
	O-T59X	●		3360,3009	