

**KMP**<sup>®</sup>  
know how in modern printing

ES MUSS NICHT ORIGINAL SEIN.



THE PERFECT ALTERNATIVE.



Product News  
October-December 2018

ERSETZT/REPLACES KMP CODE FARBE/COLOR SEITEN/PAGES\* PASSEND FÜR/SUITABLE FOR ART.-NR./ART. NO.

INKJET

Brother LC-3217BK	B58B	●	550	Brother MFC-J5330DW/MFC-J5335DW/	1537,4801
LC-3217C	B58C	●	550	MFC-J5730DW/MFC-J5930DW/MFC-J6530DW/	1538,4803
LC-3217M	B58M	●	550	MFC-J6930DW/MFC-J6935DW	1538,4806
LC-3217Y	B58Y	●	550		1538,4809
LC-3217	B58V	●●●●	4x 550		1537,4805
LC-3217BK	B58D	●●	2x 550		1537,4821
Brother LC-3219XLBK	B58BX	●	3.000	Brother MFC-J5330DW/MFC-J5335DW/	1537,4001
LC-3219XLC	B58CX	●	1.500	MFC-J5730DW/MFC-J5930DW/MFC-J6530DW/	1538,4003
LC-3219XLM	B58MX	●	1.500	MFC-J6930DW/MFC-J6935DW	1538,4006
LC-3219XLY	B58YX	●	1.500		1538,4009
LC-3219XL	B58VX	●●●●	1x 3.000, 3x 1.500		1537,4005
LC-3219XLBK	B58DX	●●	2x 3.000		1537,4021
HP 903XL (T6M15AE)	H176BX	●	1.300	HP Officejet 6950 All-in-One,	1756,0201
HP 903XL (T6M03AE)	H176CX	●	900	Officejet Pro 6970 All-in-One	1757,0003
HP 903XL (T6M07AE)	H176MX	●	900		1757,0006
HP 903XL (T6M11AE)	H176YX	●	900		1757,0009
HP 903XL (3HZ51AE)	H176VX	●●●●	1x 1.300, 3x 900		1756,0005
HP 903XL (1CC20AE)	H176CMYX	●●●	3x 900		1757,0050
HP 907XL (T6M19AE)	H177X	●	1.500	HP Officejet Pro 6960/6970	1758,4001

TONER, TROMMELEINHEITEN/DRUMS

Brother TN-3480	B-T96	●	8.000	Brother DCP-L5500dn/DCP-L6600dw, etc.	1263,0000
Brother TN-3512	B-T95	●	12.000	Brother DCP-L6600DW, HL-L6250dn etc.	1263,3000
Canon 040BK (0460C001)	C-T42B	●	6.300	Canon i-Sensys LBP710cx, LBP712cx	3608,0000
040C (0458C001)	C-T42C	●	5.400		3608,0003
040M (0456C001)	C-T42M	●	5.400		3608,0006
040Y (0454C001)	C-T42Y	●	5.400		3608,0009
Canon 040HBK (0461C001)	C-T42BX	●	12.500	Canon i-Sensys LBP710cx, LBP712cx	3608,3000
040HC (0459C001)	C-T42CX	●	10.000		3608,3003
040HM (0457C001)	C-T42MX	●	10.000		3608,3006
040HY (0455C001)	C-T42YX	●	10.000		3608,3009
Samsung CLT-K404S/ELS   SU100A	SA-T89	●	1.500	Samsung Xpress C430/C430W/C480/C480FN/	3528,0000
CLT-C404S/ELS   ST966A	SA-T90	●	1.000	C480FW/C480W	3528,0003
CLT-M404S/ELS   SU234A	SA-T91	●	1.000		3528,0006
CLT-Y404S/ELS   SU444A	SA-T92	●	1.000		3528,0009
Samsung CLT-K503L/ELS   SU147A	SA-T99B	●	8.000	Samsung ProXpress C3010ND/C3060FR	3530,0000
CLT-C503L/ELS   SU014A	SA-T99C	●	5.000		3530,0003
CLT-M503L/ELS   SU281A	SA-T99M	●	5.000		3530,0006
CLT-Y503L/ELS   SU491A	SA-T99Y	●	5.000		3530,0009
Samsung MLT-D201S/ELS   SU878A	SA-T96A	●	10.000	Samsung ProXpress M4030ND/M4080FX	3529,0000
Samsung MLT-R204/SEE   SV140A	SA-DR72		30.000	Samsung ProXpress M3325ND/M3375FD etc.	3516,7000
Samsung CLT-R406/SEE   SU403A	SA-DR92		16.000	Samsung CLP-365/CLP-365W, CLX-3305 etc.	3510,7000

ERSETZT/REPLACES KMP CODE FARBE/COLOR PASSEND FÜR/SUITABLE FOR ART.-NR./ART. NO.

INKJET

Canon PGI-580XXL PGBK (1970C001)	C110	●		Canon PIXMA TR7550/TR8550, PIXMA TS6150/	1576,0201
CLI-581XXL BK (1998C001)	C111	●		TS6151/TS6250/TS6251/TS8150/TS8151/TS8152/	1577,0201
CLI-581XXL C (1995C001)	C112	●		TS8250/TS8251/TS8252/TS9150/TS9155/TS9550/	1578,0203
CLI-581XXL M (1996C001)	C113	●		TS9551	1578,0206
CLI-581XXL Y (1997C001)	C114	●			1578,0209
CLI-581XXL BK,	C111V	●●●●			1577,0205
CLI-581XXL C/M/Y					
Epson 673 (T6731)	E225B	●		Epson L800/L805/L810/L850/L1800 IST	1639,0001
673 (T6732)	E225C	●			1639,0003
673 (T6733)	E225M	●			1639,0006
673 (T6734)	E225Y	●			1639,0009
673 (T6735)	E225LC	●			1639,0043
673 (T6736)	E225LM	●			1639,0046
Epson 102 (T03R1)	E182	●		Epson Ecotank ET-2700/ET-2750/ET-3700/ET-3750/	1642,0001
102 (T03R2)	E183	●		ET-4750	1642,0003
102 (T03R3)	E184	●			1642,0006
102 (T03R4)	E185	●			1642,0009
Epson 105 (T00Q1)	E186	●		Epson Ecotank ET-7700/ET-7750	1643,0001
106 Photo (T00R1)	E187	●			1644,0040
106 (T00R2)	E188	●			1644,0003
106 (T00R3)	E189	●			1644,0006
106 (T00R4)	E190	●			1644,0009
HP 981A (J3M71A)	H169B	●		HP Pagewide Enterprise Color 556dn/556xh,	1754,4801
HP 981A (J3M68A)	H169C	●		Pagewide Enterprise Color MFP 586dn/586f/586z	1755,4803
HP 981A (J3M69A)	H169M	●			1755,4806
HP 981A (J3M70A)	H169Y	●			1755,4809
HP 981X (L0R12A)	H169BX	●		HP Pagewide Enterprise Color 556dn/556xh,	1754,4001
HP 981X (L0R09A)	H169CX	●		Pagewide Enterprise Color MFP 586dn/586f/586z	1755,4003
HP 981X (L0R10A)	H169MX	●			1755,4006
HP 981X (L0R11A)	H169YX	●			1755,4009
HP 981Y (L0R16A)	H169BXX	●		HP Pagewide Enterprise Color 556dn/556xh,	1754,4201
HP 981Y (L0R13A)	H169CXX	●		Pagewide Enterprise Color MFP 586dn/586f/586z	1755,4203
HP 981Y (L0R14A)	H169MXX	●			1755,4206
HP 981Y (L0R15A)	H169YXX	●			1755,4209

\*nach/acc to. ISO/IEC 24711, nach/acc to. ISO/IEC 19752, 19798

ERSETZT/REPLACES	KMP CODE	FARBE/COLOR	PASSEND FÜR/SUITABLE FOR	ART.-NR./ART. NO.
------------------	----------	-------------	--------------------------	-------------------

## TONER

Canon 041 (0452C002) 041H (0453C002)	C-T44	●	Canon i-Sensys LBP312x	3610,0000
	C-T44X	●		3610,3000
Canon 052 (2199C002) 052H (2200C002)	C-T43	●	Canon Canon i-Sensys LBP212dw/LBP214dw/LBP215x, i-Sensys MF421dw/MF426dw/MF428x/MF429x	3609,0000
	C-T43X	●		3609,3000
Brother DR-3400	B-DR28		Brother DCP-L5500DN/DCP-L6600DW, HL-L5000D/ HL-L5100DN/HL-L5100DNT/HL-L5100DNTT/HL-L5200DW/ HL-L6250DN/HL-L6300DW/HL-L6400DW/HL-L6400DWT, MFC-L5700DN/MFC-L5750DW/MFC-L6800DW/ MFC-L6800DWT/MFC-L6900DW	1263,7000
Brother TN-2410 TN-2420	B-T67	●	Brother DCP-L2510D/DCP-L2530DW/DCP-L2550DN, HL-L2310D/HL-L2350DW/HL-L2370DN/HL-L2375DW, MFC-L2710DN/MFC-L2710DW/MFC-L2730DW/MFC-L2750DW	1267,0000
	B-T68	●		1267,3000
Oki 46490404 46490403 46490402 46490401	O-T53	●	Oki C532dn/C542dn, MC563dn/MC573dn	3361,0000
	O-T54	●		3361,0003
	O-T55	●		3361,0006
	O-T56	●		3361,0009
Oki 46490608 46490607 46490606 46490605	O-T53X	●	Oki C532dn/C542dn, MC563dn/MC573dn	3361,3000
	O-T54X	●		3361,3003
	O-T55X	●		3361,3006
	O-T56X	●		3361,3009

