

**KMP**<sup>®</sup>

know how in modern printing



ES MUSS NICHT ORIGINAL SEIN.



THE PERFECT ALTERNATIVE.



Product News  
April-June 2019

INKJET

TONER

THERMAL  
TRANSFER

NYLON

FRANKING  
SUPPLIES

OFFICE  
MEDIA

POS

...

ERSETZT/REPLACES	KMP CODE	FARBE/ COLOR	SEITEN/ PAGES* (CA.)	PASSEND FÜR/ SUITABLE FOR	ART.-NR./ ART. NO.	
<b>INKJET</b>						
Brother LC-223BK LC-223C LC-223M LC223Y 2x LC-223BK LC-223	R	B62BX	●	550	Brother DCP-J562DW/DCP-J4120DW,	1529,4001
		B62CX	●	550	MFC-J480DW/MFC-J680DW/	1529,4003
		B62MX	●	550	MFC-J4420DW/MFC-J880DW/	1529,4006
		B62YX	●	550	MFC-J4625DW/MFC-J4620DW/	1529,4009
		B62DX B62VX	● ● ● ● ● ●	2x 550 4x 550	MFC-J5320DW/MFC-J5625DW/ MFC-J5620DW/MFC-J5720DW	1529,4021 1529,4005
Brother LC-225XLC LC-225XLM LC-225XLY LC-225XLC/M/Y	R	B63C	●	1.200	Brother DCP-J4120DW/MFC-J4420DW/	1530,4003
		B63M	●	1.200	MFC-J4620DW/MFC-J4625DW/	1530,4006
		B63Y	●	1.200	MFC-J5320DW/MFC-J5620DW/	1530,4009
		B63V	● ● ●	3x 1.200	MFC-J5625DW/MFC-J5720DW	1530,4050
Epson 102 (T03R1) 102 (T03R2) 102 (T03R3) 102 (T03R4)	R	E182	●	7.500	Epson Ecotank ET-2700/ET-2750/ET-3700/	1642,0001
		E183	●	6.000	ET-3750/ET-4750	1642,0003
		E184	●	6.000		1642,0006
		E185	●	6.000		1642,0009
		E191 E192 E193 E194	● ● ● ●	4.500 7.500 7.500 7.500	Epson EcoTank ET-2710/ET-2711	1648,0001 1648,0003 1648,0006 1648,0009
Epson 104 (T00P1) 104 (T00P2) 104 (T00P3) 104 (T00P4)		E191	●	4.500	Epson EcoTank ET-2710/ET-2711	1648,0001
		E192	●	7.500		1648,0003
		E193	●	7.500		1648,0006
		E194	●	7.500		1648,0009
		E186 E187 E188 E189 E190	● ● ● ● ●	8.000 5.000 5.000 5.000 5.000	Epson Ecotank ET-7700/ET-7750	1643,0001 1644,0040 1644,0003 1644,0006 1644,0009
Epson 673 (T6731) 673 (T6732) 673 (T6733) 673 (T6734) 673 (T6735) 673 (T6736)		E225B	●	2.600	Epson L800/L805/L810/L850/L1800 IST	1639,0001
		E225C	●	4.700		1639,0003
		E225M	●	4.700		1639,0006
		E225Y	●	4.700		1639,0009
		E225LC	●	4.700		1639,0043
		E225LM	●	4.700		1639,0046
HP 981A (J3M71A) HP 981A (J3M68A) HP 981A (J3M69A) HP 981A (J3M70A)	R	H169B	●	6.000	HP Pagewide Enterprise Color 556dn/	1754,4801
		H169C	●	6.000	556xh, Pagewide Enterprise Color MFP	1755,4803
		H169M	●	6.000	586dn/586f/586z	1755,4806
		H169Y	●	6.000		1755,4809
HP 981X (L0R12A) HP 981X (L0R09A) HP 981X (L0R10A) HP 981X (L0R11A)	R	H169BX	●	11.000	HP Pagewide Enterprise Color 556dn/	1754,4001
		H169CX	●	10.000	556xh, Pagewide Enterprise Color MFP	1755,4003
		H169MX	●	10.000	586dn/586f/586z	1755,4006
		H169YX	●	10.000		1755,4009
HP 981Y (L0R16A) HP 981Y (L0R13A) HP 981Y (L0R14A) HP 981Y (L0R15A)	R	H169BXX	●	20.000	HP Pagewide Enterprise Color 556dn/	1754,4201
		H169CXX	●	16.000	556xh, Pagewide Enterprise Color MFP	1755,4203
		H169MXX	●	16.000	586dn/586f/586z	1755,4206
		H169YXX	●	16.000		1755,4209

● black | ● cyan | ● magenta | ● yellow | ● light/photo black | ● light/photo cyan | ● light/photo magenta | ● blue | ● color  
 R recycles Produkt/recycled product, wiederaufbereitetes Produkt/remanufactured product

INKJET

TONER

THERMAL  
TRANSFER

NYLON

FRANKING  
SUPPLIES

OFFICE  
MEDIA

POS

...

ERSETZT/REPLACES	KMP CODE	FARBE/ COLOR	SEITEN/ PAGES* (CA.)	PASSEND FÜR/ SUITABLE FOR	ART.-NR./ ART. NO.	
<b>TONER, TROMMELEINHEITEN/DRUMS</b>						
Canon 041 (0452C002) 041H (0453C002)	R	C-T44	●	10.000	Canon i-Sensys LBP312x	3610,0000
		C-T44X	●	20.000		3610,3000
Canon 052 (2199C002) 052H (2200C002)	R	C-T43	●	3.100	Canon i-Sensys LBP212dw/LBP214dw/	3609,0000
		C-T43X	●	9.200	LBP215x, i-Sensys MF421dw/MF426dw/ MF428x/MF429x	3609,3000
Brother TN-421BK TN-421C TN-421M TN-421Y	R	B-T98	●	3.000	Brother DCP-L8410CDW, HL-L8260CDW/	1265,0000
		B-T99	●	1.800	HL-L8360CDW, MFC-L8690CDW/	1265,0003
		B-T100	●	1.800	MFC-L8900CDW	1265,0006
		B-T101	●	1.800		1265,0009
Brother TN-423BK TN-423C TN-423M TN-423Y	R	B-T98X	●	6.500	Brother DCP-L8410CDW, HL-L8260CDW/	1265,3000
		B-T99X	●	4.000	HL-L8360CDW, MFC-L8690CDW/	1265,3003
		B-T100X	●	4.000	MFC-L8900CDW	1265,3006
		B-T101X	●	4.000		1265,3009
Brother DR-1050	R	B-DR29		10.000	Brother HL-1110/HL-1112/HL-1210W/ HL-1212W, DCP-1510/DCP-1512/DCP-1610W/ DCP-1612W, MFC-1810/MFC-1910W	1260,7000
HP 87A (CF287A) HP 87A (CF287A)	R	H-T238A	●	9.000	HP LaserJet Pro M501n/M501dn, Enterprise	2540,0000
		H-T243A	●	12.000	M506dn/M506x, MFP M527dn/M527f, Flow MFP M527c	2450,3000
Samsung MLT-D201L/ELS   SU870A	R	SA-T96X	●	22.000	Samsung ProXpress M4030ND/M4080FX	3529,3000
Oki 46508716 46508715 46508714 46508713 46508712 46508711 46508710 46508709	R	O-T51	●	1.500	OKI C332dn/C332dnw, MC363dn/MC363dnw	3360,0000
		O-T57	●	1.500		3360,0003
		O-T58	●	1.500		3360,0006
		O-T59	●	1.500		3360,0009
		O-T51X	●	3.500		3360,3000
		O-T57X	●	3.000		3360,3003
		O-T58X	●	3.000		3360,3006
		O-T59X	●	3.000		3360,3009

\*nach/acc to. ISO/IEC 24711, nach/acc to. ISO/IEC 19752, 19798



ERSETZT/REPLACES

KMP  
CODE

FARBE/  
COLOR

PASSEND FÜR/  
SUITABLE FOR

ART.-NR./  
ART. NO.

## INKJET

<b>Brother LC-3233BK</b> LC-3233C LC-3233M LC-3233Y	R	B79	●	Brother DCP-J1100DW, MFC-J1300DW	1541,4801
		B80	●		1542,4803
		B81	●		1542,4806
		B82	●		1542,4809
<b>Brother LC-3235XL-BK</b> LC-3235XL-C LC-3235XL-M LC-3235XL-Y	R	B83	●	Brother DCP-J1100DW, MFC-J1300DW	1541,4001
		B84	●		1542,4003
		B85	●		1542,4006
		B86	●		1542,4009
<b>Epson 34XL (T3471)</b> 34XL (T3472) 34XL (T3473) 34XL (T3477)	R	E222X	●	Epson Workforce Pro WF-3720DWF/WF-3725DWF	1637,4001
		E223X	●		1637,4003
		E224X	●		1637,4006
		E225X	●		1637,4009
<b>Epson 35XL (T3591)</b> 35XL (T3592) 35XL (T3593) 35XL (T3594)	R	E226X	●	Epson Workforce Pro WF-4720DWF&/WF-4725DWF/ WF-4730DTWF/WF-4740DTWF	1638,4001
		E227X	●		1638,4003
		E228X	●		1638,4006
		E229X	●		1638,4009
<b>HP 903XL (T6M15AE)</b> HP 903XL (T6M03AE) HP 903XL (T6M07AE) HP 903XL (T6M11AE)	R	H177BX	●	HP Officejet 6950 All-in-One, Officejet Pro 6970 All-in-One	1756,4001
		H177CX	●		1757,4003
		H177MX	●		1757,4006
		H177YX	●		1757,4009

## TONER, TROMMELEINHEITEN/DRUMS

<b>Brother DR-3400</b>	R	B-DR28		Brother DCP-L5500DN/DCP-L6600DW, HL-L5000D/ HL-L5100DN/HL-L5100DNT/HL-L5100DNNT/ HL-L5200DW/HL-L6250DN/HL-L6300DW/HL-L6400DW/ HL-L6400DWT, MFC-L5700DN/MFC-L5750DW/ MFC-L6800DW/MFC-L6800DWT/MFC-L6900DW	1263,7000
<b>Brother DR-2400</b>	R	B-DR30		Brother DCP-L2510D/DCP-L2530DW/DCP-L2550DN, HL-L2310D/HL-L2350DW/HL-L2370DN/HL-L2375DW, MFC-L2710DN/MFC-L2710DW/MFC-L2730DW/ MFC-L2750DW	1267,7000
<b>Brother TN-243BK</b> TN-243C TN-243M TN-243Y TN-247BK TN-247C TN-247M TN-247Y	R	B-T109	●	Brother DCP-L3510CDW/DCP-L3550CDW, HL-L3210CW/ HL-L3230CDW/HL-L3270CDW, MFC-L3710CW/ MFC-L3730CDN/MFC-L3750CDW/MFC-L3770CDW	1268,0000
		B-T110	●		1268,0003
		B-T111	●		1268,0006
		B-T112	●		1268,0009
		B-T109X	●		1268,3000
		B-T110X	●		1268,3003
		B-T111X	●		1268,3006
		B-T112X	●		1268,3009
<b>HP 37A (CF237A)</b>	R	H-T248	●	HP Laserjet Enterprise Flow MFP M631h/M632z, Laserjet Enterprise M607dn/M607n/M608dn/M608n/M608x/M609dn/ M609x, MFP M631dn/M631z/M632fht/M632h	2544,0000
<b>Samsung</b> MLT-D203E/ELS   SU885A MLT-D203U/ELS   SU916A	R	SA-T104	●	Samsung ProXpress SL-M3820DW/SL-M3820ND/ SL-M3820ND/SL-M3870FD/SL-M3870FW/SL-M4020ND/ SL-M4020ND/SL-M4020ND/SL-M4020NX/SL-M4070FR/ SL-M4070FX	3521,0000
		SA-T105	●		3521,3000

● black | ● cyan | ● magenta | ● yellow | ● light/photo black | ● light/photo cyan | ● light/photo magenta | ● blue | ● color  
 R recycletes Produkt/recycled product, wiederaufbereitetes Produkt/remanufactured product